
INDUSTRIAL RAILWAY SOCIETY PHOTOGRAPHIC SERVICE

KEVIN LANE COLLECTION; List no.8 (March 2022)

Available from: Kevin Lane, 15 Beech Green, Dunstable, Bedfordshire, LU6 1EB. Tel: 01582 601458

JW Greaves, Llechwedd Slate Quarries	THE COALITION, 0.4.0WE (rebuild of 0.4.0ST WB1278/98), LH ¾ front view, preserved at mine entrance, 22/6/76	K3439
	4wBE (BEV), LH view, 22/6/76	K3440
	THE ECLIPSE, 0.4.0WE (rebuild of 0.4.0ST WB1445/95), RH ¾ front view, 22/6/76	K3441
	General view of Main No.5 Level, with THE ECLIPSE, 22/6/76	K3443
	A slab of slate leaving mine on double-flanged, rope-hauled wagon, 22/6/76	K3444
	Ex-Festiniog Railway slate wagon, 22/6/76	K3447
	4wBE (WR) shunting ex-FR wagons of finished slate, 22/6/76	K3448
	Iron double-flanged tubs of waste slate, 22/6/76	K3449
	4wWE (WR640/26), OOU in shed, 22/6/76	K3451
	View of mill building on Main (No.5) Level, 13/10/77	K5296
	Line of wagons of finished slate, 13/10/77	K5298
	Bi-lingual notice of blasting times, 13/10/77	K5299
	Rebuilding plate on THE ECLIPSE, 13/10/77	K5301
	Another view of THE ECLIPSE, LH ¾ front view, 13/10/77	K5302
	Aerial view of Main No.5 Level, 13/10/77	K5303
	Wagon turntable, 13/10/77	K5305
	Rear view of THE ECLIPSE, with OOU 4wBE (WR), 13/10/77	K5308
Derelict loading dock (with crane) at former BR exchange sidings at Blaenau Festiniog	K5373	
Redland Bricks, Nutbourne Brickworks	4wDM (MR5862/34), RH ¾ front view, OOU, 18/8/77	K5062
	4wDM (MR7199/37), RH ¾ front view with loaded train, 18/8/77	K5064
	4WDM (MR8678/41), LH ¾ front view with loaded train, works behind, 18/8/78	K5071
	4wDM (MR21513/55), RH ¾ front view with train, 29/8/79	K8717
	4wDM (MR8678/41), RH ¾ front view with wagons at working face being loaded by RB bucket, 29/8/79	K8719
	BEV-built rubber-tyred transfer/traverser vehicle, 29/8/79	K8724
JW Greaves, Maenofferen Slate Quarries	A long line of empty wagons at bottom of incline, 13/10/77	K5318
	Slate cutter at bottom of incline, 13/10/77	K5321
	Wagons under unloading gantry, 13/10/77	K5323
	View up incline from bottom, 13/10/77	K5324
	View down incline from halfway, 13/10/77	K5325
	View down incline from top, 13/10/77	K5327
	Drum house, 13/10/77	K5328
	View of line between incline head and mill, 13/10/77	K5329
	General view of mill and yard, 13/10/77	K5334
	Man-rider at incline head into mine, 13/10/77	K5337
	View inside mill, 13/10/77	K5338
	4wDM (RH175127/35), LH ¾ front view, 13/10/77	K5346
General view of mill area, 13/10/77	K5351	

New Manod Slate Quarry	4wBE (BE16303/17), LH ¾ front view outside shed, 13/10/77	K5357
Milton Hall (Southend) Brick Co., Ltd., Cherry Orchard Brickworks	4wDM (MR21520/55), RH rear view, wagons being loaded from stockpile, 17/8/78	K6802
	4wDM (MR8614/41) undergoing engine change inside workshop, 17/8/78	K6807
Milton Hall (Southend) Brick Co., Ltd., Star Lane Brickworks	4wDM (RH441951/60), LH ¾ rear view with wagons being loaded from stockpile, 17/8/78	K6808
	4wDM (RH441951/60), LH ¾ front view with train at tipping shed, 17/8/78	K6811
Port of Preston	ENERGY, 4wDH (RR10281/68), RH ¾ rear view shunting tank wagons, 26/10/78	K6938
	PROGRESS, 4wDH (RR10283/68), LH ¾ front view, 26/10/78	K6951
Pressed Steel Fisher, Swindon	0.4.0DH (JF4220018/61), RH ¾ front view, 28/3/79	K7517
	0.4.0DH (JF4220032/65), RH ¾ front view with wagons of scrap, 28/3/79	K7525
	0.4.0DH (JF210105/55+JF4210137/58+JF4220017/61), RH ¾ front line up, all OOU, 28/3/79	K7527
	0.4.0DH (JF4220017/61), RH ¾ front view, 28/3/79	K7529
Coopers (Metals), Swindon	0.4.0DM (JF4210082/53), RH ¾ front view, 28/3/79	K7530
BREL, Swindon	4719, 0.8.0DH (HE9019/79), RH ¾ front view, nearing completion, 28/3/79	K7570
Aberllefeni Slate Quarries	Derelict incline rising above main yard, 10/6/79	K8066
	Wagon on incline, with turntable on top, 10/6/79	K8069
	View of line beside road between quarry and mill, 10/6/79	K8075
Forestry Commission, Aberangll	Flat wagon on small length of track between sawmill and crane, 10/6/79	K8078
Redland Bricks, North Holmwood Brickworks	4wBE (WR4998/53), LH ¾ rear view with train at working face being loaded by RB bucket, 29/8/79	K8707
	Loaded skip ascending incline towards tipping shed, 29/8/79	K8713
British Gypsum, Mountfield	4wDH (TH183v+184v/67), LH ¾ front with train of PGA wagons, 30/8/79	K8761
Redland Bricks, Crowborough Brickworks	4wBE (WR T8033/79), LH broadside view, 30/8/79	K8762
	0.4.0BE (WR M7535/72), RH ¾ front view, propelling stacking wagons, 30/8/79	K8764
	0.4.0BE (WR4634/51), RH ¾ front view, 30/8/79	K8770
Redland Bricks, Lingfield Brickworks	Home-built 4wBE, LH ¾ rear view under charge, 30/8/79	K8773
	Home-built 4wBE, LH ¾ front view sitting on transfer vehicle, 30/8/79	K8775
British Gypsum, Erith	4wDM (RH512572/65), 0.4.0DM (AB376/48) and 4wDM (RH338416/53), LH ¾ front view, lined up near to BR connection, 11/10/79	K 8978

KL-08